Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: CARLSON 2-36

Field Name: BATTLEVIEW Well File #: 8000

Date Incident: 4/29/2015 Time Incident: 13:15 Facility ID Number:

County: WILLIAMS Twp: 159 Rng: 95 Sec: 36 Qtr: NE NW

Location Description:

Submitted By: William Jansky Received By:

Contact Person: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON, TX 77060

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 1 Barrels

Oil 1 Barrels

Brine 1 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/14/2016 Clean Up Concluded: 5/15/2015

Risk Evaluation:

None. .

Areal Extent:

10 feet x 70 feet area on downhill slope of field.

Potential Environmental Impacts:

Minimal. All pooled liquids removed. Flow line cleared of production stream fluids.

Action Taken or Planned:

Area will be excavated and any contaminated soil removed. Flow line will be repaired or replaced after evaluation.

Wastes Disposal Location: PDI

Agencies Involved:

Updates

Date: 4/30/2015 Status: Reviewed - Follow-up Required Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release due to pipeline leak on pipeline ROW. Followup is necessary.

Date: 5/13/2015 Status: Inspection Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

5/13/2015 at 15:19, on location. Site of release ~800 ft southeast of wellhead in direction of tank battery within tilled field. Area has been filled back in. No visible staining in area of release.